

Fig.1








Fig.4







Fig.5



The first trees were the first of the first







REFERENCE NUMERALS

- 1. Reference subject
- 2. X-ray photographic sensor
- 3. Model subject of step-wise configuration (Subject body) 5

7/7

- 4. Correction factor setting unit
- 5. Correction factor storage unit
- 52. Correction factor storage unit
- 6. Correctional operation unit
- 10 7. Selection unit
 - 100. X-ray irradiation unit
 - 200. Controller
 - 202. Controller
 - 300. Display unit
- 15 400. Schematically illustrated subject